

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 0793 | HC1 | | 806.05 | 1 | E24 |
| 1410 | RC2 | | 1360.2 | 1 | E24 |
| 1410 | RC4 | | 1360.2 | 1 | E24 |
| 1519 | 100 | | 90.68 | 2 | E24 |
| 1519 | 200 | | 90.68 | 2 | E24 |
| 1701 | 1RS | | 1560.71 | 1 | E24 |
| 1710 | 10U | | 2724.43 | 1 | E24 |
| 1722 | 60U | | 2594.46 | 1 | E24 |
| 1723 | HC1 | | 151.13 | 1 | E24 |
| 1726 | HC2 | | 1486.15 | 3 | E24 |
| 1726 | HC3 | | 1863.98 | 3 | E24 |
| 1726 | HC4 | | 1863.98 | 3 | E24 |
| 1727 | HC1 | | 725.44 | 3 | E24 |
| 1733 | 1RU | | 725.44 | 1 | E24 |
| 1733 | HC1 | | 725.44 | 1 | E24 |
| 1735 | HC1 | | 120.91 | 1 | E24 |
| 1740 | 1RU | | 906.8 | 1 | E24 |
| 1740 | 710 | | 784.89 | 1 | E24 |
| 1742 | 1RU | | 1167.76 | 1 | E24 |
| 1742 | 90U | | 891.69 | 1 | E95 |
| 1742 | 90U | | 1337.03 | 1 | E24 |
| 1746 | C2A | | 604.53 | 3 | E24 |
| 1746 | C2A | | 435.26 | 3 | E95 |
| 1746 | E2A | | 528.97 | 3 | E24 |
| 1746 | E2A | | 380.86 | 3 | E95 |
| 1750 | 511 | | 7003.53 | 3 | E24 |
| 1750 | 522 | | 6671.03 | 3 | E24 |
| 1750 | EX1 | | 3669.52 | 3 | E24 |
| 1750 | EX2 | | 3393.45 | 3 | E24 |
| 1812 | 81A | | 1450.88 | 3 | E95 |
| 1812 | 81A | | 1882.32 | 3 | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 1812 | 81S | | 1882.32 | 3 | E24 |
| 1814 | 20A | | 4358.69 | 3 | E24 |
| 1814 | 52A | | 2075.57 | 3 | E24 |
| 1814 | 70A | | 3528.46 | 3 | E24 |
| 1814 | 70S | | 3528.46 | 3 | E24 |
| 1814 | 72A | | 4358.69 | 3 | E24 |
| 1814 | 72S | | 4358.69 | 3 | E24 |
| 1815 | 80A | | 4172.29 | 3 | E24 |
| 1815 | 82A | | 4172.29 | 3 | E24 |
| 1815 | 82A | | 3004.53 | 3 | E95 |
| 1815 | 84A | | 4944.08 | 3 | E24 |
| 1815 | 88A | | 7845.84 | 3 | E24 |
| 2005 | B16 | | 317.38 | 2 | E95 |
| 2005 | B16 | | 444.33 | 2 | E24 |
| 2005 | B32 | | 1481.11 | 2 | E95 |
| 2005 | B5K | | 1198.99 | 2 | E95 |
| 2005 | B64 | | 3050.88 | 2 | E24 |
| 2005 | B64 | | 2179.35 | 2 | E95 |
| 2005 | R18 | | 2887.66 | 2 | E95 |
| 2026 | 416 | | 871.54 | 2 | E95 |
| 2026 | 432 | | 1307.81 | 2 | E95 |
| 2053 | 424 | | 180.35 | | E95 |
| 2053 | | 4001 | 45.34 | | E95 |
| 2053 | | 4002 | 114.86 | | E95 |
| 2053 | | 4005 | 52.39 | | E95 |
| 2053 | | 4011 | 423.17 | | E95 |
| 2053 | | 4020 | 709.32 | | E95 |
| 2053 | | 4111 | 404.03 | | E95 |
| 2076 | 112 | | 3526.45 | 3 | E24 |
| 2076 | 112 | | 2518.89 | 3 | E95 |
| 2076 | 124 | | 4937.03 | 3 | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 2076 | 124 | | 3526.45 | 3 | E95 |
| 2076 | 212 | | 1625.19 | 3 | E24 |
| 2076 | 212 | | 1160.71 | 3 | E95 |
| 2076 | 224 | | 2844.33 | 3 | E24 |
| 2076 | 224 | | 2031.23 | 3 | E95 |
| 2076 | 312 | | 4937.03 | 3 | E24 |
| 2076 | 312 | | 3526.45 | 3 | E95 |
| 2076 | 324 | | 6911.84 | 3 | E24 |
| 2076 | 324 | | 4937.03 | 3 | E95 |
| 2076 | | 3504 | 987.41 | | E24 |
| 2076 | | 3504 | 705.29 | | E95 |
| 2109 | | 3226 | 141.06 | | E95 |
| 2212 | | 3200 | 317.38 | | E95 |
| 2452 | 650 | | 1375.31 | 3 | E24 |
| 2452 | 650 | | 982.37 | 3 | E95 |
| 2452 | 680 | | 1544.58 | 3 | E24 |
| 2452 | 680 | | 1103.27 | 3 | E95 |
| 2452 | | 1001 | 355.67 | | E24 |
| 2452 | | 1001 | 253.9 | | E95 |
| 2452 | | 1010 | 559.19 | | E24 |
| 2452 | | 1010 | 398.99 | | E95 |
| 2498 | B24 | | 453.4 | 2 | E95 |
| 2498 | B24 | | 634.76 | 2 | E24 |
| 2498 | B40 | | 1088.16 | 2 | E95 |
| 2498 | B80 | | 4836.27 | 2 | E95 |
| 2498 | E32 | | 6770.78 | 2 | E24 |
| 2498 | E32 | | 4836.27 | 2 | E95 |
| 3020 | HC1 | | 806.05 | 1 | E24 |
| 3151 | 310 | | 44.33 | 1 | E95 |
| 3153 | BA3 | | 101.76 | 1 | E95 |
| 3153 | BG3 | | 101.76 | 1 | E95 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 3153 | BW3 | | 101.76 | 1 | E95 |
| 3153 | CA3 | | 101.76 | 1 | E95 |
| 3153 | CG3 | | 101.76 | 1 | E95 |
| 3153 | CW3 | | 101.76 | 1 | E95 |
| 3172 | | 2001 | 176.32 | | E24 |
| 3172 | | 2002 | 634.76 | | E24 |
| 3172 | | 2210 | 24.18 | | E24 |
| 3172 | | 2215 | 148.11 | | E24 |
| 3172 | | 2220 | 69.52 | | E24 |
| 3172 | | 2225 | 69.52 | | E24 |
| 3172 | | 2230 | 173.3 | | E24 |
| 3172 | | 2240 | 173.3 | | E24 |
| 3172 | | 2250 | 4088.66 | | E24 |
| 3172 | | 2300 | 183.38 | | E24 |
| 3172 | | 2310 | 207.56 | | E24 |
| 3172 | | 2501 | 69.52 | | E24 |
| 3172 | | 2750 | 154.16 | | E24 |
| 3172 | | 2752 | 126.95 | | E24 |
| 3172 | | 2800 | 1714.86 | | E24 |
| 3172 | | 2801 | 788.92 | | E24 |
| 3172 | | 2810 | 47.36 | | E24 |
| 3172 | | 2815 | 58.44 | | E24 |
| 3172 | | 2830 | 491.69 | | E24 |
| 3172 | | 2855 | 489.67 | | E24 |
| 3172 | | 2900 | 85.64 | | E24 |
| 3172 | | 2910 | 85.64 | | E24 |
| 3172 | | 2920 | 85.64 | | E24 |
| 3174 | 01L | | 235.77 | 2 | E24 |
| 3174 | 01R | | 215.62 | 2 | E24 |
| 3174 | 02R | | 215.62 | 2 | E24 |
| 3174 | 03R | | 267 | 2 | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 3174 | 11L | | 235.77 | 2 | E24 |
| 3174 | 11R | | 235.77 | 2 | E24 |
| 3174 | 13R | | 267 | 2 | E24 |
| 3174 | 14R | | 267 | 2 | E24 |
| 3174 | 21L | | 235.77 | 2 | E24 |
| 3174 | 21R | | 215.62 | 2 | E24 |
| 3174 | 22L | | 293.2 | 2 | E24 |
| 3174 | 23R | | 293.2 | 2 | E24 |
| 3174 | 24R | | 267 | 2 | E24 |
| 3174 | 51R | | 182.37 | 2 | E24 |
| 3174 | 53R | | 235.77 | 2 | E24 |
| 3174 | 61R | | 182.37 | 2 | E24 |
| 3174 | 62R | | 182.37 | 2 | E24 |
| 3174 | 63R | | 235.77 | 2 | E24 |
| 3174 | 64R | | 235.77 | 2 | E24 |
| 3174 | 81R | | 151.13 | 2 | E24 |
| 3174 | 81S | | 137.03 | 2 | E24 |
| 3174 | 90R | | 262.97 | 2 | E24 |
| 3174 | 91R | | 151.13 | 2 | E24 |
| 3174 | 95R | | 239.8 | 2 | E24 |
| 3174 | | 1011 | 34.26 | | E24 |
| 3174 | | 1012 | 68.51 | | E24 |
| 3174 | | 1014 | 110.83 | | E24 |
| 3174 | | 1016 | 147.1 | | E24 |
| 3174 | | 1046 | 100.76 | | E24 |
| 3174 | | 1048 | 100.76 | | E24 |
| 3174 | | 1056 | 119.9 | | E24 |
| 3174 | | 3020 | 119.9 | | E24 |
| 3174 | | 3025 | 136.02 | | E24 |
| 3174 | | 3026 | 136.02 | | E24 |
| 3174 | | 3044 | 71.54 | | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 3174 | | 3045 | 71.54 | | E24 |
| 3174 | | 3050 | 66.5 | | E24 |
| 3174 | | 3051 | 66.5 | | E24 |
| 3174 | | 3053 | 66.5 | | E24 |
| 3174 | | 3055 | 293.2 | | E24 |
| 3174 | | 3100 | 98.74 | | E24 |
| 3174 | | 3103 | 16.12 | | E24 |
| 3174 | | 3105 | 73.55 | | E24 |
| 3174 | | 3110 | 59.45 | | E24 |
| 3174 | | 3680 | 20.15 | | E24 |
| 3174 | | 4710 | 265.99 | | E24 |
| 3174 | | 4730 | 336.52 | | E24 |
| 3174 | | 4740 | 336.52 | | E24 |
| 3205 | 100 | | 345.59 | 1 | E24 |
| 3206 | 110 | | 142.07 | 1 | E24 |
| 3206 | 11S | | 305.29 | 1 | E24 |
| 3299 | 001 | | 23.17 | 2 | E95 |
| 3299 | 002 | | 23.17 | 1 | E95 |
| 3299 | 003 | | 27.2 | 1 | E95 |
| 3299 | 32T | | 89.67 | 1 | E95 |
| 3361 | HC1 | | 3476.07 | 1 | E24 |
| 3362 | HC1 | | 1006.55 | 1 | E24 |
| 3363 | A01 | | 286.15 | 2 | E24 |
| 3363 | A11 | | 286.15 | 2 | E24 |
| 3476 | BA1 | | 79.6 | 1 | E95 |
| 3476 | BA3 | | 79.6 | 1 | E95 |
| 3476 | BG1 | | 79.6 | 1 | E95 |
| 3476 | BG3 | | 79.6 | 1 | E95 |
| 3476 | EA1 | | 79.6 | 1 | E95 |
| 3476 | EA3 | | 79.6 | 1 | E95 |
| 3476 | EG1 | | 79.6 | 1 | E95 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 3476 | EG3 | | 79.6 | 1 | E95 |
| 3488 | V43 | | 85.64 | 1 | E95 |
| 3488 | V51 | | 54.41 | 1 | E95 |
| 3488 | V53 | | 95.72 | 1 | E95 |
| 3489 | V11 | | 40.3 | 1 | E95 |
| 3489 | V13 | | 45.34 | 1 | E95 |
| 3489 | V1Z | | 20.15 | 1 | E95 |
| 3489 | V41 | | 60.45 | 1 | E95 |
| 3489 | V43 | | 89.67 | 1 | E95 |
| 3489 | V51 | | 60.45 | 1 | E95 |
| 3489 | V53 | | 100.76 | 1 | E95 |
| 3542 | 2RU | | 1777.33 | 1 | E24 |
| 3552 | 1RU | | 1849.87 | 1 | E24 |
| 3560 | 1RU | | 784.89 | 1 | E24 |
| 3572 | S3H | | 700.25 | 1 | E95 |
| 3572 | S4H | | 700.25 | 1 | E95 |
| 3573 | L2U | | 846.35 | 1 | E95 |
| 3573 | L2U | | 1184.89 | 1 | E24 |
| 3573 | L4U | | 1650.38 | 1 | E95 |
| 3573 | L4U | | 2310.33 | 1 | E24 |
| 3580 | H11 | | 1175.82 | 1 | E95 |
| 3580 | H13 | | 1175.82 | 1 | E95 |
| 3580 | H23 | | 889.67 | 1 | E95 |
| 3580 | H3V | | 885.64 | 2 | E24 |
| 3580 | H3V | | 632.75 | 2 | E95 |
| 3580 | H4V | | 885.64 | 2 | E24 |
| 3580 | H4V | | 632.75 | 2 | E95 |
| 3580 | L11 | | 1175.82 | 1 | E95 |
| 3580 | L13 | | 1175.82 | 1 | E95 |
| 3580 | L23 | | 889.67 | 1 | E95 |
| 3580 | L33 | | 846.35 | 1 | E95 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 3580 | L43 | | 1364.23 | 2 | E24 |
| 3580 | L43 | | 974.31 | 2 | E95 |
| 3580 | S43 | | 974.31 | 2 | E95 |
| 3580 | S53 | | 1364.23 | 1 | E24 |
| 3580 | S53 | | 974.31 | 1 | E95 |
| 3581 | F28 | | 1955.67 | 1 | E95 |
| 3581 | F38 | | 1898.24 | 1 | E95 |
| 3581 | H13 | | 2486.65 | 1 | E95 |
| 3581 | H17 | | 2702.27 | 1 | E95 |
| 3581 | H23 | | 2161.21 | 1 | E95 |
| 3581 | L13 | | 2486.65 | 1 | E95 |
| 3581 | L17 | | 2486.65 | 1 | E95 |
| 3581 | L23 | | 1879.09 | 1 | E95 |
| 3581 | L28 | | 1629.22 | 1 | E95 |
| 3581 | L38 | | 1629.22 | 1 | E95 |
| 3582 | L23 | | 2161.21 | 2 | E95 |
| 3583 | | 8103 | 192.44 | | E24 |
| 3583 | | 8104 | 192.44 | | E24 |
| 3583 | | 8105 | 252.9 | | E24 |
| 3745 | 130 | | 2620.65 | 3 | E24 |
| 3745 | 150 | | 2811.08 | 3 | E24 |
| 3745 | 170 | | 2620.65 | 3 | E24 |
| 3745 | 17A | | 2620.65 | 3 | E24 |
| 3745 | 210 | | 4177.33 | 3 | E24 |
| 3745 | 21A | | 4177.33 | 3 | E24 |
| 3745 | 310 | | 4177.33 | 3 | E24 |
| 3745 | 31A | | 4177.33 | 3 | E24 |
| 3745 | 410 | | 6427.2 | 3 | E24 |
| 3745 | 41A | | 6427.2 | 3 | E24 |
| 3745 | 610 | | 6427.2 | 3 | E24 |
| 3745 | 61A | | 6427.2 | 3 | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 3745 | | 1561 | 208.56 | | E24 |
| 3745 | | 1562 | 247.86 | | E24 |
| 3745 | | 1563 | 208.56 | | E24 |
| 3745 | | 1571 | 240.81 | | E24 |
| 3745 | | 1573 | 240.81 | | E24 |
| 3745 | | 1581 | 285.14 | | E24 |
| 3745 | | 4720 | 220.65 | | E24 |
| 3745 | | 4721 | 220.65 | | E24 |
| 3745 | | 4740 | 378.84 | | E24 |
| 3745 | | 4741 | 378.84 | | E24 |
| 3745 | | 4760 | 395.97 | | E24 |
| 3745 | | 4770 | 574.31 | | E24 |
| 3745 | | 4771 | 574.31 | | E24 |
| 3745 | | 4780 | 574.31 | | E24 |
| 3745 | | 4781 | 574.31 | | E24 |
| 3745 | | 4900 | 117.88 | | E24 |
| 3745 | | 4901 | 319.4 | | E24 |
| 3745 | | 4902 | 60.45 | | E24 |
| 3745 | | 4903 | 49.37 | | E24 |
| 3745 | | 4911 | 30.23 | | E24 |
| 3745 | | 4931 | 30.23 | | E24 |
| 3745 | | 4941 | 30.23 | | E24 |
| 3745 | | 4942 | 30.23 | | E24 |
| 3745 | | 5020 | 804.03 | | E24 |
| 3745 | | 5021 | 804.03 | | E24 |
| 3745 | | 7100 | 93.7 | | E24 |
| 3745 | | 7101 | 93.7 | | E24 |
| 3745 | | 7200 | 214.61 | | E24 |
| 3745 | | 7825 | 246.85 | | E24 |
| 3745 | | 7865 | 356.68 | | E24 |
| 3745 | | 8320 | 39.29 | | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 3746 | 900 | | 2487.66 | 3 | E24 |
| 3746 | 950 | | 2487.66 | 3 | E24 |
| 3746 | A11 | | 56.42 | 3 | E24 |
| 3746 | A12 | | 56.42 | 3 | E24 |
| 3746 | L13 | | 56.42 | 3 | E24 |
| 3746 | L14 | | 56.42 | 3 | E24 |
| 3746 | | 1561 | 189.42 | | E24 |
| 3746 | | 1562 | 225.69 | | E24 |
| 3746 | | 1571 | 240.81 | | E24 |
| 3746 | | 1581 | 271.03 | | E24 |
| 3746 | | 3251 | 224.69 | | E24 |
| 3746 | | 3286 | 537.03 | | E24 |
| 3746 | | 3288 | 155.16 | | E24 |
| 3746 | | 3289 | 310.33 | | E24 |
| 3746 | | 3297 | 288.16 | | E24 |
| 3746 | | 3299 | 235.77 | | E24 |
| 3746 | | 3520 | 95.72 | | E24 |
| 3746 | | 4720 | 201.51 | | E24 |
| 3746 | | 4900 | 108.82 | | E24 |
| 3746 | | 4901 | 290.18 | | E24 |
| 3746 | | 4911 | 29.22 | | E24 |
| 3746 | | 4931 | 29.22 | | E24 |
| 3746 | | 4941 | 29.22 | | E24 |
| 3746 | | 4942 | 29.22 | | E24 |
| 3746 | | 5000 | 586.4 | | E24 |
| 3746 | | 5005 | 219.65 | | E24 |
| 3746 | | 5015 | 965.24 | | E24 |
| 3746 | | 5021 | 804.03 | | E24 |
| 3746 | | 5022 | 1837.78 | | E24 |
| 3746 | | 5050 | 197.48 | | E24 |
| 3746 | | 5053 | 1001.51 | | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 3746 | | 5200 | 596.47 | | E24 |
| 3746 | | 5202 | 89.67 | | E24 |
| 3746 | | 5210 | 118.89 | | E24 |
| 3746 | | 5212 | 55.42 | | E24 |
| 3746 | | 5423 | 1837.78 | | E24 |
| 3746 | | 5501 | 196.47 | | E24 |
| 3746 | | 5502 | 223.68 | | E24 |
| 3746 | | 5522 | 482.62 | | E24 |
| 3746 | | 5601 | 196.47 | | E24 |
| 3746 | | 5602 | 439.29 | | E24 |
| 3746 | | 5622 | 960.2 | | E24 |
| 3746 | | 5713 | 98.74 | | E24 |
| 3746 | | 7825 | 224.69 | | E24 |
| 3746 | | 7865 | 325.44 | | E24 |
| 3758 | L32 | | 1002.52 | 2 | E95 |
| 3868 | 001 | | 199.5 | 2 | E95 |
| 3868 | 002 | | 199.5 | 2 | E95 |
| 3868 | 003 | | 220.65 | 2 | E95 |
| 3868 | 004 | | 220.65 | 2 | E95 |
| 4125 | | 3101 | 100.76 | | E24 |
| 4190 | AC1 | | 302.27 | 1 | E24 |
| 4190 | MC1 | | 302.27 | 1 | E24 |
| 4192 | AC1 | | 463.48 | 1 | E24 |
| 4192 | MC1 | | 463.48 | 1 | E24 |
| 4193 | AC1 | | 463.48 | 1 | E24 |
| 4193 | MC1 | | 463.48 | 1 | E24 |
| 4194 | AC1 | | 302.27 | 1 | E24 |
| 4194 | MC1 | | 302.27 | 1 | E24 |
| 4251 | AC1 | | 231.74 | 1 | E24 |
| 4251 | MC1 | | 231.74 | 1 | E24 |
| 4252 | AC1 | | 231.74 | 1 | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 4252 | MC1 | | 231.74 | 1 | E24 |
| 4362 | AC1 | | 503.78 | 1 | E24 |
| 4362 | MC1 | | 503.78 | 1 | E24 |
| 4363 | AC1 | | 503.78 | 1 | E24 |
| 4363 | MC1 | | 503.78 | 1 | E24 |
| 4364 | AC1 | | 503.78 | 1 | E24 |
| 4364 | MC1 | | 503.78 | 1 | E24 |
| 4365 | AC1 | | 503.78 | 1 | E24 |
| 4365 | MC1 | | 503.78 | 1 | E24 |
| 4367 | AC1 | | 221.66 | 1 | E24 |
| 4367 | MC1 | | 221.66 | 1 | E24 |
| 4368 | AC1 | | 221.66 | 1 | E24 |
| 4368 | MC1 | | 221.66 | 1 | E24 |
| 4610 | DG3 | | 106.8 | 1 | E95 |
| 4610 | DG4 | | 131.99 | 1 | E95 |
| 4610 | DI3 | | 106.8 | 1 | E95 |
| 4610 | DI4 | | 131.99 | 1 | E95 |
| 4610 | DM6 | | 110.83 | 1 | E24 |
| 4610 | IF6 | | 115.87 | 1 | E24 |
| 4610 | TF6 | | 85.64 | 1 | E95 |
| 4610 | TF7 | | 68.51 | 1 | E95 |
| 4610 | TG3 | | 145.09 | 1 | E24 |
| 4610 | TG4 | | 179.34 | 1 | E24 |
| 4610 | TI1 | | 152.14 | 1 | E24 |
| 4610 | TI2 | | 188.41 | 1 | E24 |
| 4610 | TI3 | | 145.09 | 1 | E24 |
| 4610 | TI4 | | 179.34 | 1 | E24 |
| 4610 | TM6 | | 115.87 | 1 | E24 |
| 4610 | TM7 | | 92.7 | 1 | E24 |
| 4610 | TN4 | | 207.56 | 1 | E24 |
| 4610 | TO3 | | 96.73 | 1 | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 4610 | TS1 | | 231.74 | 1 | E24 |
| 4610 | TS2 | | 301.26 | 1 | E24 |
| 4610 | TS3 | | 220.65 | 1 | E24 |
| 4610 | TS4 | | 287.15 | 1 | E24 |
| 4610 | | 3201 | 38.29 | | E24 |
| 4610 | | 3206 | 38.29 | | E24 |
| 4610 | | 3324 | 51.39 | | E24 |
| 4610 | | 3380 | 25.19 | | E24 |
| 4610 | | 3381 | 25.19 | | E24 |
| 4610 | | 3382 | 25.19 | | E24 |
| 4610 | | 3383 | 25.19 | | E24 |
| 4610 | | 3391 | 25.19 | | E24 |
| 4610 | | 3392 | 25.19 | | E24 |
| 4610 | | 3565 | 36.27 | | E24 |
| 4610 | | 3575 | 28.21 | | E24 |
| 4610 | | 3580 | 22.17 | | E24 |
| 4610 | | 3845 | 52.39 | | E24 |
| 4610 | | 3850 | 52.39 | | E24 |
| 4610 | | 3875 | 52.39 | | E24 |
| 4610 | | 3935 | 92.7 | | E24 |
| 4610 | | 3936 | 92.7 | | E24 |
| 4610 | | 4780 | 25.19 | | E24 |
| 4610 | | 4781 | 25.19 | | E24 |
| 4610 | | 4880 | 25.19 | | E24 |
| 4610 | | 4881 | 25.19 | | E24 |
| 4610 | | 5950 | 27.2 | | E24 |
| 4610 | | 5965 | 41.31 | | E24 |
| 4610 | | 5970 | 41.31 | | E24 |
| 4610 | | 5975 | 98.74 | | E24 |
| 4610 | | 5980 | 98.74 | | E24 |
| 4667 | HC9 | | 8060.45 | 1 | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 4667 | HCD | | 50377.83 | 1 | E24 |
| 4667 | HCE | | 17128.46 | 1 | E24 |
| 4667 | HCM | | 2518.89 | 1 | E24 |
| 4667 | HCN | | 1813.6 | 1 | E24 |
| 4667 | HCP | | 1813.6 | 1 | E24 |
| 4667 | HCQ | | 1813.6 | 1 | E24 |
| 4668 | HC5 | | 1209.07 | 1 | E24 |
| 4668 | HC6 | | 120.91 | 1 | E24 |
| 4669 | HCB | | 4030.23 | 1 | E24 |
| 4669 | HCL | | 1209.07 | 1 | E24 |
| 4669 | HCM | | 1209.07 | 1 | E24 |
| 4670 | HC9 | | 4030.23 | 1 | E24 |
| 4670 | HCA | | 8060.45 | 1 | E24 |
| 4670 | HCB | | 17128.46 | 1 | E24 |
| 4670 | HCC | | 1511.34 | 1 | E24 |
| 4670 | HCD | | 8060.45 | 1 | E24 |
| 4670 | HCE | | 1511.34 | 1 | E24 |
| 4670 | HCF | | 8060.45 | 1 | E24 |
| 4670 | HCL | | 8060.45 | 1 | E24 |
| 4670 | HCM | | 17128.46 | 1 | E24 |
| 4670 | HCP | | 33249.37 | 1 | E24 |
| 4670 | HCQ | | 14105.79 | 1 | E24 |
| 4800 | 741 | | 165.24 | 1 | E24 |
| 4800 | | 3050 | 41.31 | | E24 |
| 4800 | | 3057 | 41.31 | | E24 |
| 4800 | | 3120 | 56.42 | | E24 |
| 4800 | | 3124 | 51.39 | | E24 |
| 4800 | | 3206 | 38.29 | | E24 |
| 4800 | | 3315 | 22.17 | | E24 |
| 4800 | | 3320 | 31.23 | | E24 |
| 4800 | | 3323 | 69.52 | | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 4800 | | 3324 | 38.29 | | E24 |
| 4800 | | 3325 | 0 | | E24 |
| 4800 | | 3565 | 36.27 | | E24 |
| 4800 | | 3566 | 36.27 | | E24 |
| 4800 | | 3575 | 28.21 | | E24 |
| 4800 | | 3576 | 28.21 | | E24 |
| 4800 | | 3580 | 22.17 | | E24 |
| 4800 | | 3780 | 69.52 | | E24 |
| 4800 | | 3845 | 57.43 | | E24 |
| 4800 | | 3846 | 52.39 | | E24 |
| 4800 | | 3850 | 52.39 | | E24 |
| 4800 | | 3875 | 52.39 | | E24 |
| 4800 | | 3946 | 51.39 | | E24 |
| 4800 | | 3947 | 51.39 | | E24 |
| 4800 | | 3948 | 56.42 | | E24 |
| 4800 | | 4361 | 28.21 | | E24 |
| 4800 | | 4369 | 25.19 | | E24 |
| 4800 | | 4780 | 25.19 | | E24 |
| 4800 | | 4781 | 25.19 | | E24 |
| 4800 | | 4880 | 28.21 | | E24 |
| 4800 | | 4881 | 28.21 | | E24 |
| 4800 | | 4882 | 25.19 | | E24 |
| 4800 | | 5400 | 19.14 | | E24 |
| 4800 | | 5501 | 20.15 | | E24 |
| 4800 | | 5502 | 23.17 | | E24 |
| 4800 | | 5503 | 13.1 | | E24 |
| 4800 | | 5950 | 27.2 | | E24 |
| 4800 | | 5951 | 27.2 | | E24 |
| 4800 | | 5955 | 50.38 | | E24 |
| 4800 | | 5960 | 37.28 | | E24 |
| 4800 | | 5961 | 37.28 | | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 4800 | | 5965 | 41.31 | | E24 |
| 4800 | | 5966 | 41.31 | | E24 |
| 4800 | | 5970 | 41.31 | | E24 |
| 4800 | | 5971 | 41.31 | | E24 |
| 4800 | | 5975 | 98.74 | | E24 |
| 4800 | | 5980 | 98.74 | | E24 |
| 4800 | | 7355 | 34.26 | | E24 |
| 4800 | | 7360 | 34.26 | | E24 |
| 4800 | | 7580 | 32.24 | | E24 |
| 4800 | | 7585 | 28.21 | | E24 |
| 4800 | | 7800 | 30.23 | | E24 |
| 4800 | | 7911 | 41.31 | | E24 |
| 4800 | | 7912 | 18.14 | | E24 |
| 4800 | | 7921 | 41.31 | | E24 |
| 4800 | | 7931 | 43.32 | | E24 |
| 4800 | | 7941 | 43.32 | | E24 |
| 4800 | | 7951 | 47.36 | | E24 |
| 4800 | | 7956 | 47.36 | | E24 |
| 4800 | | 7961 | 47.36 | | E24 |
| 4800 | | 7966 | 47.36 | | E24 |
| 4800 | | 7971 | 47.36 | | E24 |
| 4800 | | 7975 | 53.4 | | E24 |
| 4800 | | 7976 | 47.36 | | E24 |
| 4800 | | 7980 | 53.4 | | E24 |
| 4800 | | 7981 | 47.36 | | E24 |
| 4800 | | 7982 | 47.36 | | E24 |
| 4800 | | 7985 | 36.27 | | E24 |
| 4800 | | 7987 | 36.27 | | E24 |
| 4800 | | 7989 | 42.32 | | E24 |
| 4835 | 120 | | 513.85 | 1 | E24 |
| 4835 | 150 | | 528.97 | 1 | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 4835 | 152 | | 561.21 | 1 | E24 |
| 4835 | 153 | | 534 | 1 | E24 |
| 4835 | | 2200 | 22.17 | | E24 |
| 4835 | | 3300 | 97.73 | | E24 |
| 4835 | | 3301 | 97.73 | | E24 |
| 4835 | | 3302 | 97.73 | | E24 |
| 4835 | | 4709 | 462.47 | | E24 |
| 4835 | | 4710 | 540.05 | | E24 |
| 4835 | | 4900 | 462.47 | | E24 |
| 4835 | | 4901 | 540.05 | | E24 |
| 4835 | | 5000 | 112.85 | | E24 |
| 4835 | | 7699 | 30.23 | | E24 |
| 4835 | | 7800 | 80.6 | | E24 |
| 4840 | 532 | | 258.94 | 1 | E95 |
| 4840 | 53R | | 349.62 | 1 | E24 |
| 4840 | 542 | | 283.12 | 1 | E95 |
| 4840 | 54R | | 382.87 | 1 | E24 |
| 4840 | 552 | | 283.12 | 1 | E95 |
| 4840 | 55R | | 382.87 | 1 | E24 |
| 4840 | 562 | | 365.74 | 1 | E95 |
| 4840 | 56R | | 494.71 | 1 | E24 |
| 4840 | 622 | | 253.9 | 1 | E95 |
| 4840 | 62R | | 343.58 | 1 | E24 |
| 4840 | 642 | | 455.42 | 1 | E95 |
| 4840 | 64R | | 455.42 | 1 | E24 |
| 4840 | 652 | | 455.42 | 1 | E95 |
| 4840 | 65R | | 455.42 | 1 | E24 |
| 4840 | | 1252 | 30.23 | | E95 |
| 4840 | | 1255 | 30.23 | | E95 |
| 4840 | | 1256 | 36.27 | | E95 |
| 4840 | | 1261 | 96.73 | | E95 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 4840 | | 1262 | 163.22 | | E95 |
| 4840 | | 1263 | 229.72 | | E95 |
| 4840 | | 1264 | 296.22 | | E95 |
| 4840 | | 1265 | 362.72 | | E95 |
| 4840 | | 1266 | 429.22 | | E95 |
| 4840 | | 1267 | 495.72 | | E95 |
| 4840 | | 1268 | 562.22 | | E95 |
| 4840 | | 3057 | 41.31 | | E24 |
| 4840 | | 3061 | 41.31 | | E24 |
| 4840 | | 3100 | 22.17 | | E95 |
| 4840 | | 3103 | 22.17 | | E95 |
| 4840 | | 4781 | 18.14 | | E95 |
| 4840 | | 4881 | 20.15 | | E95 |
| 4840 | | 5900 | 9.07 | | E95 |
| 4840 | | 5910 | 9.07 | | E95 |
| 4840 | | 5920 | 15.11 | | E95 |
| 4840 | | 7800 | 37.28 | | E95 |
| 5494 | EXT | | 322.42 | 2 | E24 |
| 5821 | 010 | | 29.22 | 2 | E95 |
| 5822 | 010 | | 78.59 | 2 | E95 |
| 5822 | 018 | | 115.87 | 2 | E95 |
| 6217 | AC1 | | 200.5 | 1 | E95 |
| 6217 | MC1 | | 200.5 | 1 | E95 |
| 6218 | AC1 | | 200.5 | 1 | E95 |
| 6218 | MC1 | | 200.5 | 1 | E95 |
| 6223 | AC1 | | 200.5 | 1 | E95 |
| 6223 | MC1 | | 200.5 | 1 | E95 |
| 6546 | 0AZ | | 59.45 | 1 | E95 |
| 7141 | AC1 | | 1813.6 | 1 | E24 |
| 7141 | AC2 | | 1813.6 | 1 | E24 |
| 7141 | MC1 | | 1813.6 | 1 | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 7141 | MC2 | | 1813.6 | 1 | E24 |
| 7163 | AC1 | | 1309.82 | 1 | E24 |
| 7163 | MC1 | | 1309.82 | 1 | E24 |
| 7248 | | 4279 | 64.48 | | E24 |
| 7321 | AC1 | | 332.49 | 1 | E24 |
| 7323 | AC1 | | 332.49 | 1 | E24 |
| 7327 | AC1 | | 221.66 | 1 | E24 |
| 7327 | MC1 | | 221.66 | 1 | E24 |
| 7328 | AC1 | | 221.66 | 1 | E24 |
| 7328 | MC1 | | 221.66 | 1 | E24 |
| 7596 | | 6075 | 2098.74 | | E24 |
| 7596 | | 6082 | 78.59 | | E24 |
| 7596 | | 6186 | 78.59 | | E24 |
| 7596 | | 6187 | 89.67 | | E24 |
| 7596 | | 6261 | 88.66 | | E24 |
| 7596 | | 6285 | 107.81 | | E24 |
| 7596 | | 6433 | 184.38 | | E24 |
| 7596 | | 6435 | 78.59 | | E24 |
| 7596 | | 6440 | 184.38 | | E24 |
| 7596 | | 6442 | 78.59 | | E24 |
| 7596 | | 6446 | 1115.37 | | E24 |
| 7596 | | 6461 | 88.66 | | E24 |
| 7596 | | 6483 | 107.81 | | E24 |
| 7596 | | 6487 | 147.1 | | E24 |
| 7596 | | 6608 | 144.08 | | E24 |
| 7596 | | 6612 | 144.08 | | E24 |
| 7596 | | 6618 | 144.08 | | E24 |
| 7596 | | 6833 | 23.17 | | E24 |
| 7778 | 23X | | 604.53 | 1 | E24 |
| 7778 | | 8273 | 1088.16 | | E24 |
| 7778 | | 8446 | 256.93 | | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 7779 | BCS | | 1511.34 | 1 | E24 |
| 7809 | H22 | | 302.27 | 1 | E24 |
| 7825 | RC1 | | 755.67 | 1 | E24 |
| 7831 | HC1 | | 36.27 | 1 | E24 |
| 7833 | AC1 | | 332.49 | 1 | E24 |
| 7836 | AC1 | | 403.02 | 1 | E24 |
| 7836 | MC1 | | 403.02 | 1 | E24 |
| 7837 | AC1 | | 403.02 | 1 | E24 |
| 7837 | MC1 | | 403.02 | 1 | E24 |
| 7839 | AC1 | | 680.1 | 1 | E24 |
| 7839 | MC1 | | 680.1 | 1 | E24 |
| 7852 | 400 | | 38.29 | 1 | E95 |
| 7852 | 40Z | | 38.29 | 1 | E95 |
| 7861 | 014 | | 51.39 | 2 | E24 |
| 7861 | 015 | | 51.39 | 2 | E24 |
| 7861 | 016 | | 51.39 | 2 | E24 |
| 7861 | 024 | | 61.46 | 2 | E24 |
| 7861 | 025 | | 61.46 | 2 | E24 |
| 7861 | 026 | | 61.46 | 2 | E24 |
| 7861 | 045 | | 112.85 | 2 | E24 |
| 7861 | 046 | | 112.85 | 2 | E24 |
| 7861 | 047 | | 112.85 | 2 | E24 |
| 7861 | | 7953 | 16.12 | | E24 |
| 7866 | | 4127 | 46.35 | | E95 |
| 7868 | | 7952 | 9.07 | | E24 |
| 7868 | | 7953 | 14.11 | | E24 |
| 7870 | AC1 | | 302.27 | 1 | E24 |
| 7870 | MC1 | | 302.27 | 1 | E24 |
| 7901 | AC1 | | 302.27 | 1 | E24 |
| 7901 | MC1 | | 302.27 | 1 | E24 |
| 7902 | AC1 | | 302.27 | 1 | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|---------------------|--------------|----------------|----------------------|-----------------------|-----------------------------|
| 7902 | MC1 | | 302.27 | 1 | E24 |
| 7940 | AC1 | | 231.74 | 1 | E24 |
| 7940 | MC1 | | 231.74 | 1 | E24 |
| 7943 | AC1 | | 755.67 | 1 | E24 |
| 7943 | MC1 | | 755.67 | 1 | E24 |
| 7945 | AC1 | | 680.1 | 1 | E24 |
| 7945 | AC1 | | 453.4 | 1 | E95 |
| 7945 | MC1 | | 680.1 | 1 | E24 |
| 7945 | MC1 | | 453.4 | 1 | E95 |
| 7946 | AC1 | | 503.78 | 1 | E24 |
| 7946 | AC1 | | 335.52 | 1 | E95 |
| 7946 | MC1 | | 503.78 | 1 | E24 |
| 7946 | MC1 | | 335.52 | 1 | E95 |
| 7947 | AC1 | | 680.1 | 1 | E24 |
| 7947 | MC1 | | 680.1 | 1 | E24 |
| 7969 | AC1 | | 503.78 | 1 | E24 |
| 7969 | MC1 | | 503.78 | 1 | E24 |
| 7971 | AC1 | | 403.02 | 1 | E24 |
| 7971 | MC1 | | 403.02 | 1 | E24 |
| 7972 | AC1 | | 806.05 | 1 | E24 |
| 7972 | MC1 | | 806.05 | 1 | E24 |
| 7973 | AC1 | | 680.1 | 1 | E24 |
| 7973 | MC1 | | 680.1 | 1 | E24 |
| 7974 | AC1 | | 680.1 | 1 | E24 |
| 7974 | MC1 | | 680.1 | 1 | E24 |
| 7975 | AC1 | | 680.1 | 1 | E24 |
| 7975 | MC1 | | 680.1 | 1 | E24 |
| 7976 | AC1 | | 680.1 | 1 | E24 |
| 7976 | MC1 | | 680.1 | 1 | E24 |
| 7977 | AC1 | | 1360.2 | 1 | E24 |
| 7977 | MC1 | | 1360.2 | 1 | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 7978 | AC1 | | 503.78 | 1 | E24 |
| 7978 | MC1 | | 503.78 | 1 | E24 |
| 7979 | 21U | | 680.1 | 1 | E24 |
| 7979 | AC1 | | 680.1 | 1 | E24 |
| 7979 | MC1 | | 680.1 | 1 | E24 |
| 7981 | AC1 | | 403.02 | 1 | E24 |
| 7981 | MC1 | | 403.02 | 1 | E24 |
| 7984 | AC1 | | 503.78 | 1 | E24 |
| 7984 | MC1 | | 503.78 | 1 | E24 |
| 7985 | AC1 | | 680.1 | 1 | E24 |
| 7985 | MC1 | | 680.1 | 1 | E24 |
| 7988 | J21 | | 403.02 | 2 | E24 |
| 7989 | BCH | | 685.14 | 2 | E24 |
| 7989 | | 3248 | 967.25 | | E24 |
| 7989 | | 3248 | 644.84 | | E95 |
| 7989 | | 3284 | 926.95 | | E24 |
| 7989 | | 3284 | 617.63 | | E95 |
| 7995 | AC1 | | 403.02 | 1 | E24 |
| 7995 | MC1 | | 403.02 | 1 | E24 |
| 7996 | AC1 | | 226.7 | 1 | E24 |
| 7996 | MC1 | | 226.7 | 1 | E24 |
| 7998 | 60X | | 302.27 | 1 | E24 |
| 7998 | 61X | | 302.27 | 2 | E24 |
| 8014 | AC1 | | 226.7 | 1 | E24 |
| 8014 | MC1 | | 226.7 | 1 | E24 |
| 8028 | AC1 | | 226.7 | 1 | E24 |
| 8028 | MC1 | | 226.7 | 1 | E24 |
| 8228 | KT3 | | 91.69 | | E24 |
| 8230 | 001 | | 287.15 | 2 | E24 |
| 8230 | 002 | | 329.47 | 2 | E24 |
| 8230 | 003 | | 382.87 | 2 | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 8240 | 002 | | 1069.02 | 2 | E24 |
| 8265 | | 5008 | 1639.29 | | E24 |
| 8265 | | 5012 | 332.49 | | E24 |
| 8265 | | 5102 | 380.86 | | E24 |
| 8265 | | 5104 | 976.32 | | E24 |
| 8265 | | 5208 | 1362.22 | | E24 |
| 8265 | | 5212 | 1756.17 | | E24 |
| 8265 | | 5300 | 1005.54 | | E24 |
| 8265 | | 5308 | 1390.43 | | E24 |
| 8265 | | 5312 | 1814.61 | | E24 |
| 8265 | | 5400 | 1005.54 | | E24 |
| 8265 | | 5401 | 1005.54 | | E24 |
| 8265 | | 5403 | 1005.54 | | E24 |
| 8265 | | 5602 | 1171.79 | | E24 |
| 8265 | | 5612 | 1171.79 | | E24 |
| 8265 | | 6501 | 732.49 | | E24 |
| 8265 | | 6502 | 732.49 | | E24 |
| 8265 | | 6511 | 269.02 | | E24 |
| 8265 | | 6512 | 537.03 | | E24 |
| 8265 | | 6540 | 117.88 | | E24 |
| 8265 | | 6543 | 97.73 | | E24 |
| 8265 | | 6558 | 245.84 | | E24 |
| 8265 | | 6559 | 234.76 | | E24 |
| 8265 | | 6560 | 234.76 | | E24 |
| 8265 | | 6561 | 351.64 | | E24 |
| 8265 | | 6570 | 663.98 | | E24 |
| 8265 | | 6571 | 663.98 | | E24 |
| 8265 | | 6572 | 663.98 | | E24 |
| 8265 | | 6573 | 663.98 | | E24 |
| 8265 | | 6574 | 663.98 | | E24 |
| 8265 | | 6575 | 663.98 | | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 8265 | | 6616 | 1344.08 | | E24 |
| 8265 | | 6617 | 1576.83 | | E24 |
| 8265 | | 6670 | 773.8 | | E24 |
| 8265 | | 6671 | 773.8 | | E24 |
| 8265 | | 8707 | 62.47 | | E24 |
| 8271 | | 1330 | 341.56 | | E24 |
| 8271 | | 1340 | 80.6 | | E24 |
| 8271 | | 1345 | 113.85 | | E24 |
| 8273 | | 7115 | 29.22 | | E24 |
| 8273 | | 7116 | 29.22 | | E24 |
| 8273 | | 7117 | 166.25 | | E24 |
| 8273 | | 7118 | 52.39 | | E24 |
| 8273 | | 7119 | 52.39 | | E24 |
| 8273 | | 7123 | 201.51 | | E24 |
| 8273 | | 7125 | 855.42 | | E24 |
| 8273 | | 7126 | 689.17 | | E24 |
| 8273 | | 7127 | 510.83 | | E24 |
| 8273 | | 7128 | 344.58 | | E24 |
| 8273 | | 7129 | 344.58 | | E24 |
| 8273 | | 7130 | 689.17 | | E24 |
| 8273 | | 7131 | 344.58 | | E24 |
| 8274 | | 0562 | 767.76 | | E24 |
| 8274 | | 0582 | 727.46 | | E24 |
| 8274 | | 0583 | 706.3 | | E24 |
| 8274 | | 0584 | 1140.55 | | E24 |
| 8274 | | 0607 | 895.72 | | E24 |
| 8274 | | 0867 | 869.52 | | E24 |
| 8274 | | 2850 | 585.39 | | E24 |
| 8274 | | 2993 | 162.22 | | E24 |
| 8274 | | 2995 | 1079.09 | | E24 |
| 8274 | | 2997 | 3087.15 | | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|---------------------|--------------|----------------|----------------------|-----------------------|-----------------------------|
| 8274 | | 2999 | 1678.59 | | E24 |
| 8274 | | 3001 | 1950.63 | | E24 |
| 8274 | | 3003 | 1640.3 | | E24 |
| 8274 | | 3009 | 1019.65 | | E24 |
| 8274 | | 3013 | 1501.26 | | E24 |
| 8274 | | 3017 | 1345.09 | | E24 |
| 8274 | | 3021 | 2152.14 | | E24 |
| 8274 | | 3023 | 595.47 | | E24 |
| 8274 | | 3029 | 861.46 | | E24 |
| 8274 | | 3031 | 861.46 | | E24 |
| 8274 | | 3050 | 501.76 | | E24 |
| 8274 | | 3059 | 446.35 | | E24 |
| 8274 | | 3061 | 558.19 | | E24 |
| 8274 | | 3063 | 334.51 | | E24 |
| 8274 | | 3065 | 446.35 | | E24 |
| 8274 | | 3083 | 1535.52 | | E24 |
| 8274 | | 3169 | 797.98 | | E24 |
| 8274 | | 3171 | 945.09 | | E24 |
| 8274 | | 3725 | 767.76 | | E24 |
| 8274 | | 3726 | 756.67 | | E24 |
| 8274 | | 3727 | 1512.34 | | E24 |
| 8274 | | 6863 | 686.15 | | E24 |
| 8274 | | 6864 | 686.15 | | E24 |
| 8274 | | 6865 | 508.82 | | E24 |
| 8274 | | 6866 | 862.47 | | E24 |
| 8274 | | 6867 | 261.96 | | E24 |
| 8274 | | 6868 | 344.58 | | E24 |
| 8274 | | 6869 | 512.85 | | E24 |
| 8274 | | 6870 | 571.28 | | E24 |
| 8274 | | 6871 | 562.22 | | E24 |
| 8274 | | 6872 | 675.06 | | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|-------------------------|--------------|----------------|--------------------------|---------------------------|---------------------------------|
| 8274 | | 6873 | 797.98 | | E24 |
| 8274 | | 6874 | 1088.16 | | E24 |
| 8274 | | 6875 | 1339.04 | | E24 |
| 8274 | | 6876 | 1088.16 | | E24 |
| 8274 | | 6877 | 490.68 | | E24 |
| 8274 | | 6878 | 576.32 | | E24 |
| 8274 | | 6879 | 668.01 | | E24 |
| 8274 | | 6880 | 839.29 | | E24 |
| 8274 | | 6881 | 1336.02 | | E24 |
| 8274 | | 6882 | 1507.3 | | E24 |
| 8274 | | 6883 | 2045.34 | | E24 |
| 8274 | | 6884 | 2386.9 | | E24 |
| 8274 | | 6885 | 981.36 | | E24 |
| 8274 | | 6886 | 1152.64 | | E24 |
| 8274 | | 6887 | 1339.04 | | E24 |
| 8274 | | 6888 | 1674.56 | | E24 |
| 8274 | | 6889 | 1103.27 | | E24 |
| 8274 | | 6890 | 1576.83 | | E24 |
| 8274 | | 6891 | 1103.27 | | E24 |
| 8274 | | 6892 | 1576.83 | | E24 |
| 8274 | | 6893 | 490.68 | | E24 |
| 8274 | | 6894 | 668.01 | | E24 |
| 8274 | | 6895 | 668.01 | | E24 |
| 8274 | | 6896 | 668.01 | | E24 |
| 8274 | | 6897 | 1021.66 | | E24 |
| 8274 | | 7010 | 1001.51 | | E24 |
| 8274 | | 7012 | 778.84 | | E24 |
| 8274 | | 7013 | 1445.84 | | E24 |
| 8274 | | 7014 | 723.43 | | E24 |
| 8274 | | 7015 | 945.09 | | E24 |
| 8274 | | 7016 | 920.91 | | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 8274 | | 7017 | 920.91 | | E24 |
| 8274 | | 7018 | 920.91 | | E24 |
| 8274 | | 7019 | 834.26 | | E24 |
| 8274 | | 7021 | 445.34 | | E24 |
| 8274 | | 7024 | 869.52 | | E24 |
| 8274 | | 7025 | 328.46 | | E24 |
| 8274 | | 7026 | 668.01 | | E24 |
| 8274 | | 7027 | 646.85 | | E24 |
| 8274 | | 7028 | 646.85 | | E24 |
| 8274 | | 7051 | 1057.93 | | E24 |
| 8274 | | 7053 | 1148.61 | | E24 |
| 8274 | | 7057 | 469.52 | | E24 |
| 8274 | | 7058 | 646.85 | | E24 |
| 8274 | | 7060 | 646.85 | | E24 |
| 8274 | | 7061 | 1001.51 | | E24 |
| 8274 | | 7062 | 41.31 | | E24 |
| 8274 | | 7074 | 1146.6 | | E24 |
| 8274 | | 7075 | 490.68 | | E24 |
| 8274 | | 7076 | 1635.26 | | E24 |
| 8274 | | 7077 | 1295.72 | | E24 |
| 8274 | | 7078 | 1110.33 | | E24 |
| 8274 | | 7079 | 940.05 | | E24 |
| 8274 | | 7080 | 2346.6 | | E24 |
| 8274 | | 7081 | 2004.03 | | E24 |
| 8274 | | 7082 | 1464.99 | | E24 |
| 8274 | | 7083 | 1294.71 | | E24 |
| 8274 | | 7084 | 818.14 | | E24 |
| 8274 | | 7086 | 555.16 | | E24 |
| 8274 | | 7087 | 469.52 | | E24 |
| 8274 | | 7088 | 1048.87 | | E24 |
| 8274 | | 7089 | 1295.72 | | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 8274 | | 7090 | 1048.87 | | E24 |
| 8274 | | 7094 | 521.91 | | E24 |
| 8274 | | 7096 | 467.51 | | E24 |
| 8274 | | 7099 | 53.4 | | E24 |
| 8274 | | 7100 | 30.23 | | E24 |
| 8274 | | 7101 | 30.23 | | E24 |
| 8274 | | 7102 | 171.28 | | E24 |
| 8274 | | 7103 | 53.4 | | E24 |
| 8274 | | 7104 | 53.4 | | E24 |
| 8274 | | 7105 | 466.5 | | E24 |
| 8274 | | 7106 | 821.16 | | E24 |
| 8274 | | 7107 | 466.5 | | E24 |
| 8274 | | 7108 | 466.5 | | E24 |
| 8274 | | 7112 | 413.1 | | E24 |
| 8274 | | 7113 | 307.3 | | E24 |
| 8274 | | 7138 | 354.66 | | E24 |
| 8274 | | 7139 | 296.22 | | E24 |
| 8274 | | 7140 | 235.77 | | E24 |
| 8274 | | 7141 | 296.22 | | E24 |
| 8274 | | 7142 | 207.56 | | E24 |
| 8274 | | 8722 | 675.06 | | E24 |
| 8274 | | 8723 | 718.39 | | E24 |
| 8274 | | 8724 | 728.46 | | E24 |
| 8274 | | 8725 | 767.76 | | E24 |
| 8274 | | 8726 | 965.24 | | E24 |
| 8274 | | 8727 | 1004.53 | | E24 |
| 8274 | | 9582 | 1260.45 | | E24 |
| 8274 | | 9588 | 1260.45 | | E24 |
| 8274 | | 9590 | 1033.75 | | E24 |
| 8285 | | 5502 | 1446.85 | | E24 |
| 8406 | 70Y | | 428.21 | 1 | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 8406 | 71Y | | 806.05 | 1 | E24 |
| 8406 | | 8358 | 201.51 | | E24 |
| 8485 | AC1 | | 503.78 | 1 | E24 |
| 8485 | MC1 | | 503.78 | 1 | E24 |
| 8486 | AC1 | | 226.7 | 1 | E24 |
| 8486 | MC1 | | 226.7 | 1 | E24 |
| 8488 | AC1 | | 503.78 | 1 | E24 |
| 8488 | MC1 | | 503.78 | 1 | E24 |
| 8490 | AC1 | | 503.78 | 1 | E24 |
| 8490 | MC1 | | 503.78 | 1 | E24 |
| 8491 | AC1 | | 503.78 | 1 | E24 |
| 8491 | MC1 | | 503.78 | 1 | E24 |
| 8639 | 0E5 | | 503.78 | 1 | E24 |
| 8640 | 11Y | | 1556.67 | 1 | E24 |
| 8640 | 1Y0 | | 1556.67 | 1 | E24 |
| 8640 | PB0 | | 1556.67 | 1 | E24 |
| 8648 | AC1 | | 503.78 | 1 | E24 |
| 8648 | MC1 | | 503.78 | 1 | E24 |
| 8651 | RM0 | | 1511.33 | 1 | E24 |
| 8656 | 2RY | | 1511.33 | 1 | E24 |
| 8656 | 4RY | | 1511.33 | 1 | E24 |
| 8656 | 6RY | | 1511.33 | 1 | E24 |
| 8660 | 42U | | 1556.67 | 1 | E24 |
| 8669 | 1RX | | 680.1 | 1 | E24 |
| 8669 | 4RX | | 680.1 | 1 | E24 |
| 8677 | 2XX | | 685.14 | 1 | E24 |
| 8677 | 3RU | | 685.14 | 1 | E24 |
| 8677 | 3RU | | 456.42 | 1 | E95 |
| 8677 | 3XU | | 685.14 | 1 | E24 |
| 8677 | 3XU | | 456.42 | 1 | E95 |
| 8677 | HC1 | | 685.14 | 1 | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 8682 | 5RY | | 1511.34 | 1 | E24 |
| 8686 | 1RX | | 806.05 | 1 | E24 |
| 8686 | 8RX | | 806.05 | 1 | E24 |
| 8687 | 6RX | | 1707.81 | 1 | E24 |
| 8720 | HC1 | | 685.14 | 1 | E24 |
| 8730 | HC1 | | 685.14 | 1 | E24 |
| 8740 | HC1 | | 685.14 | 1 | E24 |
| 8750 | HC1 | | 685.14 | 1 | E24 |
| 8832 | G1X | | 403.02 | 1 | E24 |
| 8832 | L1X | | 403.02 | 1 | E24 |
| 8832 | M1X | | 403.02 | 1 | E24 |
| 8832 | M1X | | 269.02 | 1 | E95 |
| 8839 | 61X | | 403.02 | 1 | E24 |
| 8839 | 61X | | 269.02 | 1 | E95 |
| 8840 | 25U | | 680.1 | 1 | E24 |
| 8840 | 55U | | 680.1 | 1 | E24 |
| 8840 | AC1 | | 680.1 | 1 | E24 |
| 8840 | MC1 | | 680.1 | 1 | E24 |
| 8841 | AC1 | | 1360.2 | 1 | E24 |
| 8841 | MC1 | | 1360.2 | 1 | E24 |
| 8843 | 21U | | 403.02 | 1 | E24 |
| 8843 | 21U | | 269.02 | 1 | E95 |
| 8843 | 35U | | 403.02 | 1 | E24 |
| 8843 | 35U | | 269.02 | 1 | E95 |
| 8843 | 3RU | | 403.02 | 1 | E24 |
| 8843 | 3RU | | 269.02 | 1 | E95 |
| 8843 | 55U | | 403.02 | 1 | E24 |
| 8843 | 55U | | 269.02 | 1 | E95 |
| 8843 | AC1 | | 403.02 | 1 | E24 |
| 8843 | AC1 | | 269.02 | 1 | E95 |
| 8843 | MC1 | | 403.02 | 1 | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|--------------|-------|---------|---------------|----------------|----------------------|
| 8843 | MC1 | | 269.02 | 1 | E95 |
| 8849 | AC1 | | 503.78 | 1 | E24 |
| 8849 | MC1 | | 503.78 | 1 | E24 |
| 8850 | AC1 | | 403.02 | 1 | E24 |
| 8850 | MC1 | | 403.02 | 1 | E24 |
| 8852 | 4XU | | 685.14 | 1 | E24 |
| 8852 | 4XU | | 456.42 | 1 | E95 |
| 8852 | HC1 | | 685.14 | 1 | E24 |
| 8853 | AC1 | | 403.02 | 1 | E24 |
| 8853 | MC1 | | 403.02 | 1 | E24 |
| 8863 | AC1 | | 740.55 | 1 | E24 |
| 8863 | MC1 | | 740.55 | 1 | E24 |
| 8865 | AC1 | | 1511.34 | 1 | E24 |
| 8865 | MC1 | | 1511.34 | 1 | E24 |
| 8866 | AC1 | | 1511.34 | 1 | E24 |
| 8866 | MC1 | | 1511.34 | 1 | E24 |
| 8872 | AC1 | | 3627.2 | 1 | E24 |
| 8872 | MC1 | | 3627.2 | 1 | E24 |
| 8874 | AC1 | | 1813.6 | 1 | E24 |
| 8874 | MC1 | | 1813.6 | 1 | E24 |
| 8877 | AC1 | | 806.05 | 1 | E24 |
| 8877 | MC1 | | 806.05 | 1 | E24 |
| 8886 | AC1 | | 1511.34 | 1 | E24 |
| 9228 | AC1 | | 200.5 | 1 | E95 |
| 9228 | MC1 | | 200.5 | 1 | E95 |
| 9306 | RC1 | | 446.35 | 1 | E24 |
| 9307 | RC2 | | 446.35 | 1 | E24 |
| 9307 | RC4 | | 446.35 | 1 | E24 |
| 9308 | 42E | | 460.45 | 1 | E24 |
| 9308 | 42S | | 460.45 | 1 | E24 |
| 9308 | RC4 | | 460.45 | 1 | E24 |

| Machine Type | Model | Feature | Annual Charge | Per Call Class | Maintenance Offering |
|-------------------------|--------------|----------------|--------------------------|---------------------------|---------------------------------|
| 9512 | AB0 | | 130.98 | 1 | E95 |

!

!

!

!

!

!

!

!

!

!

!

!

!

!

!

!

!

!

!

!

!

!

!

!

!

!

!

!

!

!

!

!