

SF99675: 740 Hardware and Related PTFs

PTF Group Level: 2

Last Updated: 1/16/20

How to Display: WRKPTFGRP SF99675

Description: The HW Group PTF is defined to contain Hardware and PTFs related to the function of Hardware within the OS

The following Subsystems are included:

- o Disk, Disk Adapter and Disk related functions
 - + Device Parity protection
 - + Mirroring
 - + Hot Spare
 - + Disk Concurrent Maintenance
 - + Fiber-Channel Disk and Multi-path
- o LAN Adapter and LAN related functions including HEA
- o WAN adapter and WAN related functions
- o Cryptographic Coprocessor related functions
- o System Firmware and Firmware related PTFs

The HW Group PTF is defined to exclude PTFs that are higher level in function such as:

- o TCP/IP stack problems
- o System crashes except where those system crashes were the direct result of a HW related function
- o High Availability Solutions (such as GeoMirror and Independent ASPs) except where a hardware related function is the cause

HW Group does not contain

- o Tape Adapter and tape related functions
- o Fiber-Channel Tape and tape library related functions

Planned Update Schedule: The planned update schedule for this group is quarterly.

Related PTF Group(s): None

PTF ordering information:

<http://www.ibm.com/support/fixcentral/ibmi>

Links to group member PTF special instructions:

http://www.ibm.com/support/docview.wss?uid=nas4SF99675_SI

```

-----
PTF          DATE          APAR          LICENSED CUMULATIVE
NUMBER      ADDED              PROGRAM  PACKAGE
*****
MF66810     01/16/20      MA48055     5770999  0121
MF65732     07/24/19      MA47510     5770999  9151
*****

```